

Clearance between the JTT and the beampipe when the ECT is on the HF truck

